Temperature sensor type K (NiCrNi)

PAN FLÄCHENFÜHLER ohne Adapter

Temperature area sensor, K thermocouple -50° - +500°C without adapter

Temperature area sensor, K thermocouple **-50° - +500°C** (without adapter)

