Temperature sensor type K (NiCrNi)

PAN PUNKTFÜHLER-SET

Temperature point sensor, K thermocouple -50° - +250°C + adapter plug for connection to multimeter

Temperature point sensor, K thermocouple **-50° - +250°C** + adapter plug for connection to multimeter

